

# SERVICE BULLETIN

**Date:** April 6, 2015  
**Update Number:** S2015-11  
**Subject:** Wrong Output Plug  
**Products Affected:** 85LM Transformer

Recently, there have been several field reports that a small quantity of 85LM Universal Radio Control Plug-In AC Transformers have been released with an output plug that is too small to plug into the intended LiftMaster products. Only a small quantity of 85LM Transformers produced on February 6, 2015, are affected.

If you experience this issue, please contact LiftMaster Technical Support at 800.528.2806 to obtain a Return Goods Authorization for a replacement.

## 85LM TRANSFORMER

